

## LEAD SERVICE LINE INVENTORY TECHNICAL ASSISTANCE

	Lead	Galvanized Iron	Copper	Brass
Outer Appearance	Dull gray, bendable; often curves between wall/floor and valve	Dark gray or black; straight rigid pipe	Brown; can have green corrosion spots	Brown; can have green corrosion spots
Threads at Connections	None	Yes	None	Yes
Scratch Test (coin or key)	Shiny silver	Hard to scratch, remains gray	Copper, like a penny	Gold color
Magnet Test	Does not stick	Magnet WILL stick	Does not stick	Does not stick